

PlanetSafe Test & Tag

Visit summary · generated 2026-05-21 · version v2

Visit summary

Meridian Property Group · Collins St office · visit 2026-05-14

ITEMS TESTED	TEST RESULT: PASS	TEST RESULT: FAIL	TEST RESULT: INCONCLUSIVE
176	168	8	0
FAILED ITEMS RECORDED	TECHNICIAN	MANUALLY RECORDED ENTRIES	
8	R. Okafor	13	

ASSET	ITEM	FAILURE REASON	STATUS
PS-GCKYA	Pallet wrapper power unit	Insulation resistance below limit (0.62 M Ω , limit e 1.0 M Ω)	action required
PS-VWPJ5	Kettle	Insulation resistance below limit (0.62 M Ω , limit e 1.0 M Ω)	action required
PS-9AGYH	Heat gun	Insulation resistance below limit (0.62 M Ω , limit e 1.0 M Ω)	customer notified
PS-TT68C	Power board 4-way	Insulation resistance below limit	action recorded
PS-J6ZFM	Hot water urn	Insulation resistance below limit (0.62 M Ω , limit e 1.0 M Ω)	awaiting retest
PS-SGTV9	Refrigerator	Insulation resistance below limit (0.62 M Ω , limit e 1.0 M Ω)	awaiting retest
PS-XYFH6	Sandwich press	Insulation resistance below limit (0.62 M Ω , limit e 1.0 M Ω)	retested fail
PS-AZK4R	Monitor power supply	Insulation resistance below limit (0.62 M Ω , limit e 1.0 M Ω)	closed

Test results are the recorded outcome of each individual portable appliance test.