

PlanetSafe Test & Tag

Visit summary · generated 2026-02-06 · version v1

Visit summary

Meridian Property Group · Brisbane depot · visit 2026-02-06

ITEMS TESTED	TEST RESULT: PASS	TEST RESULT: FAIL	TEST RESULT: INCONCLUSIVE
71	66	4	1
FAILED ITEMS RECORDED	TECHNICIAN	MANUALLY RECORDED ENTRIES	
4	R. Okafor	7	

ASSET	ITEM	FAILURE REASON	STATUS
PS-9FCZ3	Extension lead 10 m	Insulation resistance below limit	action required
PS-5J4B8	Pallet wrapper power unit	Insulation resistance below limit (0.62 MΩ, limit e 1.0 MΩ)	customer notified
PS-8EQVF	Vacuum cleaner	Insulation resistance below limit (0.62 MΩ, limit e 1.0 MΩ)	action recorded
PS-7GT9N	Laptop charger	Insulation resistance below limit (0.62 MΩ, limit e 1.0 MΩ)	awaiting retest

Test results are the recorded outcome of each individual portable appliance test.